


Instructions for Q9 programming:

1. Acquire software: Go to flomecmeters.com and download latest version of 145600-10 software.
2. A zip file of software and required drivers will be downloaded.
3. Install on Windows® based computer that's being used for programming.
4. Remove 2 each AAA batteries from Q9 display.
5. Plug USB end of cable into computer.
6. Attach programming cable as shown below to Q9 display.
7. Launch software, wait for Q9 to power on, follow prompts to reconfigure Q9 display.
8. For questions or service contact GPI Customer Service Department in Wichita, Kansas during normal business hours. Toll Free 1-888-996-3837.



Wichita · Sydney

GREAT PLAINS INDUSTRIES



© 2021 Great Plains Industries, Inc., All Rights Reserved.
Great Plains Industries, Inc. / 888-996-3837 / flomecmeters.com